Form 3860-10 (February 1987)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Minera	1 Survey Number	
	4863	
State		
	Arizona	
Land I	District	

Arizona

FIELD NOTES

Of the Survey of the Mining Claim of (name and address of claimant)

Onanon, Inc. 1453 Trane, P. O. Box 1305 Bullhead City, Arizona 86430

Known as the (name of group, if any)

NAME OF CLAIM(S)

		DATE		BLM
NAME OF LOCATION	LOCATED AND AMENDED	RECORDED WITH COUNTY	RECORDED WITH BLM	MINING CLAIM SERIAL NUMBER
Gold Slab #1	4/23/69	4/30/69		
	6/29/79	7/05/79	8/01/79	50855
J & L #4	2/15/82	1/04/83	1/25/83	19044
J & L #7	6/25/75	6/27/75 7/05/79	8/01/79	50839
	5,25,75	,,03,,,	0,01,75	3003.

LOCATION OF CLAIM(S)

Mining district			County	
San Fran	ncisco		Mohave	
Section 11 and 12	Township 21 North	Range 21 West	Meridian G&SR	Survey under order dated January 26, 1987
Survey commenced February 28	Survey co	ompleted 23, 1987	Name of Mineral Surveyor Jack M. Kesle	

FEET

This survey was made with a Topcon TL-20DE Digital Theodolite No. A31771, with horizontal limb 2.76 ins. diam., and full vertical circle 2.76 ins. diam., both circles being read with an optical micrometer whose least count is 20 arc seconds; the instrument is equipped with a special reticle for observing the suns center; the eyepiece is equipped with a filter for observing the sun directly.

All azimuths in this record were determined by the method of double horizontal angles measured to the right referred to the meridian determined by the following observations:

On February 28, 1987, and again on March 8, 1987, at Corner No. 1 of the J & L #4 lode, in latitude 35°13'12" N, and longitude 114°28'53" W, I make a series of 18 (9D,R) hour angle observations upon the sun for azimuth, observing the center of the sun, and reading the horizontal angle to the right from a reference point 3,084 ft. southward SW to the sun.

Time of observation, UT1 universal time = $22^{h}53^{m}32.5^{s}$ (February 28, 1987)

Declination of sun at UT1 = S 7°53'22"

Horizontal angle from reference point to sun's center =

54°15'40"

Local Hour Angle of the sun at UT1 =

45°45'42"

True bearing to the reference point =

S 00°00'01" W

The mean of 18 separate observations provides a value = S 00°00'03" W with a standard error of plus or minus 03.7" yielding a final value of South.

The lines were measured with a Topcon DM-S1 Electronic Distance Meter No. B31084; which was compared with the Kingman Calibration Base Line at the time of beginning the survey, and found to be working correctly.

FEET All lines and connections of this survey were run by direct methods. The magnetic declination observed at each corner of the survey gave a uniform value of 13°48' E. Mineral Survey No. 4863 GOLD SLAB #1 LODE At Cor. No. 1 of the Gold Slab #1 lode, identical with the NW Cor. of the Gold Slab #6 lode, unsurveyed, being also identical with the 1/4 sec. cor. of secs. 11 and 12, T 21 N, R 21 W, G&SRM, Mohave County, Arizona, and on line 1-2 of the J & L #4 lode of this survey. Set an aluminum pipe, 2 3/8 ins. diam., 30 ins. long, 22 ins. in the ground with aluminum cap mkd. 1/4 T21N | R21W J | 4863 GS1 S11 1987 Thence North Enter large wash, left bank, course S 30° W. 30. Leave large wash, right bank, course S 45° W. 59. Electric line, on wooden poles, bears N 63 1/2° W and 152. S 63 1/2° E. Electric line, on wooden poles, bears N 47° E and 186. S 47° W. Lode line; discovery point bears N 86°56'30" E. 300.00 50 ft. dist. Cor. Nos. 1 and 1, of the J & L #4 lode and the 366.33 J & L #7 lode respectively, of this survey.

FEET	
453.	Enter large wash, left bank, course West.
574.05	Cor. No. 2, on line 4-1 of the J & L #7 lode, of this survey.
	Set an aluminum pipe, 2 3/8 ins. diam., 30 ins. long, 22 ins. in the ground with aluminum cap mkd.
	4 J 8 & 6 L 2 3 7 GS1 4863
	from which
	A Cor. of the location bears North, 75.2 ft. dist.
	Thence N 86°56'30" E
120.	Road, 10 ft. wide; bears N 19° W and S 19° E.
125.	Underground telephone line, bears N 19° W and S 19° E.
594.	Water line, 4 ins. diam., steel, bears N 72 1/2° W and S 72 1/2° E.
647.	Underground telephone line, bears N 72 1/2° W and S 72 1/2° E.
660.	Road, 20 ft. wide, bears N 72° W and S 72° E.
830.	Leave large wash, right bank, course West.
1334.	Wash, 3 ft. wide, course S 5° W.
1370.10	Cor. No. 3.
	Set an iron pin, 5/8 ins. diam., 8 ins. long, 4 ins. in concrete, with aluminum cap mkd.
	3 GS1 4863

FEET		-1136
198 = 1	from which	
	A Cor. of the location bears S 89°54'50" E, 20.1 ft. dist.	
	Thence South	
131.	Enter large wash, right bank, course N 75° W.	
208.	Underground telephone line, bears N 86° W and S 86° E.	
215.	Road, 20 ft. wide, bears N 80° W and S 80° E.	
228.	Water line, 4 ins. diam., steel, bears N 85° W and S 85° E.	130
274.05	Lode line, discovery point bears S 86°56'30" W, 1320.10 ft. dist.	- 14
310.	Leave large wash, left bank, course N 50° W.	
361.	Ridge, bears N 80° W and S 80° E.	
420.	Enter large wash, right bank, course S 65° W.	
563.	Leave large wash, left bank, course S 60° W.	
574.05	Cor. No. 4, identical with the SW Cor. of the Gold Slab #8 lode, the NW Cor. of the Gold Slab #7 lode, and with the NE Cor. of the Gold Slab #6 lode, all unsurveyed.	
	Set an aluminum rod, 5/8 ins. diam., 30 ins. long, 26 ins. in the ground, with aluminum cap mkd.	
	4863 GS1 4	
	Thence S 86°56'30" W	
20.	Enter large wash, left bank, course S 50° W.	
275.	Leave large wash, right bank, course S 80° W.	
805.	Wash, 16 ft. wide, course S 25° W.	

	FEET	
7 F	1095.	Electric line, on wooden poles, bears N 63 1/2° W and S 63 1/2° E.
	1370.10	Cor. No. 1, and place of beginning.
		J & L #4 LODE
		At Cor. No. 1 of the J & L #4 lode, identical with Cor. No. 1 of the J & L #7 lode of this survey, and on line 1-2 of the Gold Slab #1 lode of this survey.
		Set an aluminum pipe, 2 3/8 ins. diam., 30 ins. long, 22 ins. in the ground, with aluminum cap mkd.
		4 J&L7 1 3 8 1 S 6 6 1 G 8 3 J&L4 4
		from which
	i	The 1/4 sec. cor. of secs. 11 and 12, bears South, 366.33 ft. dist., hereinbefore described.
		Thence South
	186.	Electric line, on wooden poles, bears N 47° E and S 47° W.
	214.	Electric line, on wooden poles, bears N 63 1/2° W and S 63 1/2° E.
	307.	Enter large wash, right bank, course S 45° W.
	336.	Leave large wash, left bank, course S 30° W.
	366.33	Cor. No. 1 of the Gold Slab #1 lode of this survey.
	536.	Enter large wash, right bank, course S 50° W.
	581.	Road, 8 ft. wide, bears S 55° W and N 55° E.
	637.	Leave large wash, left bank, course S 60° W.
	761.	Wash, 7 ft. wide, course West.

FEET		
827.	Wash, 12 ft. wide, course West.	
942.	Wash, 10 ft. wide, course N 60° W.	
1065.	Enter large wash, right bank, course S 80° W.	
1131.	Leave large wash, left bank, course S 80° W.	
1351.	Enter large wash, right bank, course S 50° W.	
1392.	Leave large wash, left bank, course S 60° W.	
1451.90	Cor. No. 2, identical with the NE Cor. of the J & L #1 lode, unsurveyed.	
_1 7	Set an aluminum rod, 5/8 ins. diam., 30 ins. long, 26 ins. in the ground, with aluminum cap mkd.	
	4863 J&L4 2	
	from which	
_	The cor. of secs. 11, 12, 13, and 14, T 21 N, R 21 W, bears South, 1548.00 ft. dist., a G.L.O. brass cap, firmly set and properly mkd., as described in the official record.	
	Thence West	
70.	Road, 20 ft. wide, bears N 5°E and S 5°W.	
274.	Wash, 10 ft. wide, course S 80° W.	
300.00	Lode line, discovery point bears North, 701.90 ft. dist.	
433.	Wash, 2 ft. wide, course S 60° W.	
600.00	Cor. No. 3, identical with the NW Cor. of the J & L #1 lode, the NE Cor. of the J & L #2 lode, and the SE Cor. of the J & L #5 lode, all unsurveyed.	

FFFT		
	Set an aluminum rod, 5/8 ins. diam., 30 ins. long, 26 ins. in the ground, with aluminum cap mkd.	
	4863 J&L4 3	
	Thence North	
51.	Wash, 2 ft. wide, course S 65° W.	
291.	Wash, 2 ft. wide, course N 85° W.	
336.	Enter large wash, left bank, course S 60° W.	
364.	Leave large wash, right bank, course N 80° W.	
417.	Enter large wash, left bank, course S 50° W.	
459.	Leave large wash, right bank, course S 70° W.	
595.	Wash, 2 ft. wide, course S 70° W.	
718.	Wash, 4 ft. wide, course S 45° W.	
870.	Wash, 24 ft. wide, course S 70° W.	
1108.	Wash, 4 ft. wide, course S 45° W.	
1355.	Road, 10 ft. wide, bears N 65° E and S 75° W.	
1451.	Enter large wash, left bank, course West.	
1451.90	Cor. No. 4, identical with Cor. No. 2 of the J & L #7 lode, this survey, and identical with the NE Cor. of the J & L #8 lode, both unsurveyed.	
	Set an aluminum rod, 5/8 ins. diam., 30 ins. long, 26 ins. in the ground, with aluminum cap mkd.	
	4863 J&L7 2 4 J&L4 4863	

FEET	
	Thence East
100.	
	Leave large wash, left bank, course S 70° W.
174.	Electric line, on wooden poles, bears N 63 1/2° W and S 63 1/2° E.
300.00	Lode line, discovery point bears South, 750.00 ft. dist.
463.	Road, 20 ft. wide, bears S 10° W and N 10° E.
600.00	Cor. No. 1, and place of beginning.
2.5	J & L #7 LODE
	Beginning at Cor. No. 1 of the J & L #7 lode, identical with Cor. No. 1 of the J & L #4 lode of this survey, and on line 1-2 of the Gold Slab #1 lode of this survey.
	Thence West
137.	Road, 20 ft. wide, bears S 10° W and N 10° E.
300.00	Lode line, discovery point bears North, 750.00 ft. dist.
426.	Electric line, on wooden poles, bears N 63 1/2° W and S 63 1/2° E.
500.	Enter large wash, left bank, course S 70° W.
600.00	Cor. No. 2, identical with Cor. No. 4 of the J & L #4 lode, of this survey, and identical with the NE Cor. of the J & L #5 lode, and the SE Cor. of the J & L #8 lode, both unsurveyed.
	Thence North
74.	Leave large wash, right bank, course S 65° W.
87.	Electric line, on wooden poles, bears N 63 1/2° W and S 63 1/2° E.
186.	Ridge, bears West and East.

FEEL	
216.	Wash, 12 ft. wide, course N 60° W.
591.	Wash, 20 ft. wide, course West.
660.	Enter large wash, left bank, course N 65° W.
805.	Water line, 4 ins. diam., steel, bears N 63 1/4° W and S 63 1/4° E.
812.	Road, 20 ft. wide, bears N 60° W and S 60° E.
818.	Underground telephone line, bears N 64 1/2° W and S 64 1/2° E.
868.	Leave large wash, right bank, course N 80° W.
1041.	Enter wash, 4 ft. wide, course North.
1088.	Leave wash, 4 ft. wide, course N 45° W.
1131.	Wash, 16 ft. wide, course West.
1345.	Wash, 26 ft. wide, course S 75° W.
1500.00	Cor. No. 3.
	Set an aluminum rod, 5/8 ins. diam., 30 ins. long, 26 ins. in the ground, with aluminum cap mkd.
	3 J&L7 4863
	from which
	A Cor. of the location bears N 71°51' W, 61.0 ft. dist.
	Thence East
269.	Wash, 12 ft. wide, course S 50° W.
300.00	Lode line, discovery point bears South, 750.00 ft. dist.

FFF1		
600.00	Cor. No. 4.	
	Set an aluminum rod, 5/8 ins. diam., 30 ins. long, 26 ins. in the ground, with aluminum cap mkd.	
	J&L7 4863	
	from which	
	The cor. of secs. 1, 2, 11, and 12, T 21 N, R 21 W, bears North, 767.24 ft. dist., a G.L.O. brass cap, firmly set and properly mkd., as described in the official record.	
	A Cor. of the location bears North, 27.2 ft. dist.	
	Thence South	
294.	Wash, 5 ft. wide, course N 75° W.	
356.	Ridge, bears West and East.	
573.	Wash, 2 ft. wide, course N 50° W.	
630.	Enter Road, East edge, bears N 10° W and South.	
690.	Leave Road, East edge, bears North and S 10° W.	
764.	Enter large wash, right bank, course S 50° W.	
990.	Road, 16 ft. wide, bears N 64° W and S 64° E.	
997.	Water line, 4 ins. diam., steel, bears N 64 1/4° W and S 64 1/4° E.	
1127.	Underground telephone line, bears S 64 1/4° W and N 64 1/4° E.	
1137.	Road, 20 ft. wide, bears S 64° W and N 64° E.	
1292.28	Cor. No. 2, Gold Slab #1 lode, of this survey.	

FEET		
1413.	Leave large wash, left bank, course West.	
1500.00	Cor. No. 1, and place of beginning.	
	AREAS	
	Total area, Gold Slab #1 lode Acre	
	Total area, J & L #4 lode 19.99	
	Total area, J & L #7 lode 20.6	
- 624	LOCATION	
	This survey is located in secs. 11 and 12, T 21 N, R 21 W, G&SRM, Mohave County, Arizona.	
	The survey of the J & L #4 lode is identical with the amended location as marked on the ground. The survey of the J & L #7 lode is wholly within the amended location as marked on the ground; Cor. Nos. 1 and 2 are identical with the corners of the location; Cor. Nos. 3 and 4 differ to the extent previously shown. The survey of the Gold Slab #1 lode is wholly within the amended location as marked on the ground; Cor. Nos. 1 and 4 are identical with the corners of the location; Cor. Nos. 2 and 3 differ to the extent previously shown.	еу •
	EXPENDITURES	
	The improvements and the value of the labor and improvements made upon or for the benefit of each o the lode locations embraced in said mining claim by the claimant or its grantors are as follows:	f
No. 1	The discovery point of the Gold Slab #1 lode, being on the lode line 50 ft. from a point 300 ft. North Cor. No. 1, and 274.05 ft. South of Cor. No. 2 on line 1-2. No Value	οf
No. 2	A churn drill hole, 6 ins. in diam., 285 ft. deep, the center of which bears S 37°01' E, 265 ft. from Cor. No. 2, Gold Slab #1 lode. Value, \$3,200	

FEET		
No. 3	A reverse circulation drill hole, 6 ins. in diam., 105 ft. deep, the center of which bears S 2°32' E, 248 ft. from Cor. No. 2, Gold Slab #1 lode. Value, \$1,180	
No. 1	The discovery point of the J & L #4 lode, being on the lode line 750 ft. from the center of line 4-1. No Value	
No. 2	A churn drill hole, 6 ins. in diam., 100 ft. deep, the center of which bears S 68°33' W, 179 ft. from Cor. No. 1, J & L #4 lode. Value, \$1,120	
No. 3	A reverse circulation drill hole, 6 ins. in diam., 285 ft. deep, the center of which bears S 54°39' W, 368 ft. from Cor. No. 1, J & L #4 lode. Value, \$3,200	
No. 4	A trench, the South end of which bears N 27°54' W, 639 ft. from Cor. No. 2, J & L #4 lode; 6 ft. wide, 4 ft. deep, running N 30° W, 40 ft. Value, \$50	
No. 1	The discovery point of the J & L #7 lode, being on the lode line 750 ft. from the center of line 1-2. No Value	
No. 2	A churn drill hole, 6 ins. in diam., 140 ft. deep, the center of which bears N 8°14' W, 246 ft. from Cor. No. 1, J & L #7 lode. Value, \$1,570	
No. 3	A reverse circulation drill hole, 6 ins. in diam., 200 ft. deep, the center of which bears N 9°02' W, 238 ft. from Cor. No. 1, J & L #7 lode. Value, \$2,245	
No. 4	A churn drill hole, 6 ins. in diam., 60 ft. deep, the center of which bears N 4°18' W, 270 ft. from Cor. No. 1, J & L #7 lode. Value, \$670	
No. 5	A churn drill hole, 6 ins. in diam., 40 ft. deep, the center of which bears N 20°04' W, 289 ft. from Cor. No. 1, J & L #7 lode. Value, \$450	

FEET					
No. 6	A churn drill hole, 6 ins. in diam., 300 ft. deep, the center of which bears N 28°56' W, 205 ft. from Cor. No. 1, J & L #7 lode. Value, \$3,370				
No. 7	A reverse circulation drill hole, 6 ins. in diam., 165 ft. deep, the center of which bears N 86°36' W, 178 ft. from Cor. No. 1, J & L #7 lode. Value, \$1,850				
No. 8	A trench, the West end of which bears S 28°40' E, 690 ft. from Cor. No. 3, J & L #7 lode; 18 ft. wide, 6 ft. deep, running N 85° E, 70 ft. Value, \$300				
No. 9	A trench, the West end of which bears S 23°37' E, 654 ft. from Cor. No. 3, J & L #7 lode; 18 ft. wide, 5 ft. deep, running S 50° E, 50 ft. Value, \$100				
	OTHER IMPROVEMENTS				
	A trench, the West end of which bears S 35°23' E, 324 ft. from Cor. No. 3, J & L #7 lode; 10 ft. wide, 2 ft. deep, running N 55° E, 105 ft.				
	A shaft, 4 x 4 ft., 7 ft. deep, the center of which bears S 39°08' E, 457 ft. from Cor. No. 3, J & L #7 lode.				
	An adit, 4 x 8 ft. in size, the portal of which bears S 49°36' W, 380 ft. from Cor. No. 3, Gold Slab #1 lode, and runs S 10° W, 9 ft. to face.				
	An adit, 4 x 7 ft. in size, the portal of which bears S 50°17' W, 390 ft. from Cor. No. 3, Gold Slab #1 lode, and runs S 10° W, 7 ft. to face.				
	An adit, 4 x 7 ft. in size, the portal of which bears S 74°37' W, 708 ft. from Cor. No. 3, Gold Slab #1 lode, and runs S 10° W, 10 ft. to face.				
	Extensive: shaft, winzes, drifts, and stopes, the entrance for which was in the vicinity of the current open pit, too caved to enter and measure. Claimant of each unknown.				

FEET

Heap leaching pads, furnaces, together with auxiliary structures (watchman's trailer, supply trailers, tanks) and a water system.

Claimant herein.

OTHER CORNER DESCRIPTIONS AND SUPPLEMENTAL DATA

The bearing for the sec. line common to secs. 11 and 12 was found to be correct as approved. The length of this line was found to be 5267.14 ft. instead of 5280.00 ft., as approved.

The monument and its accessories for the 1/4 sec. cor. of secs. 11 and 12 have been destroyed. The position for which was deemed to be lost when a search of the record provided no substantial tie for considering it obliterated. Single proportionate measurement was resorted to resulting in the position shown. An approximate tie (latitude only) was found on BLM R/W No. PHX 034352. This tie distance was 153 ft. which agrees with the actual field tie of 152.33 ft.

FIELD ASSISTANTS

Derle D. Walker......Rodman
Gail Kesler.....Flagman

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

CERTIFICATE OF SURVEYOR

Name of Mineral Surveyor	Date July 4, 1987
JACK M. KESLER	3419 4, 1701
	n order received from the Arizona State
I have carefully executed the survey of	hoenix, Arizona, dated <u>January 26, 1987</u> , the claim of (owners) <u>Onanon, Inc.</u>
#1; J & L #4; J & L #7 lodes	e (lode, placer, or mill site) Gold Slab
situated in (surveyed) (unsurveyed) sec	tion(s) 11 and 12 ,
	ila and Salt River Meridian, in the State
I FURTHER CERTIFY That the labor expend the benefit of the (lode or placer) the embraced in the said mining claim by clastated in my report. The character, exspecified in full detail. No portion of improvements so credited to this claim expenditures upon any other claim.	ree (3) lode location(s) aimant(s) or its grantors are fully tent, location, and itemized value are f, or interest in, said labor and
Kingman, Arizona (Location)	(Signature of Mineral Surveyor)

Title 18, U.S.C. section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious, or fraudulent statements or representations as to any matter within its jurisdiction.

CERTIFICATE OF APPROVAL

Arizona State Office Phoenix, Arizona Date: JUL 1 3 1987

The foregoing field notes of mineral surv	vey number <u>4863</u> , in (surveyed)
(unsurveyed) section(s) 11 and 12	,
Township 21 North , Range 21 West , G	ila and Salt River Meridian, in the State
of Arizona, executed by <u>Jack M. Kesler</u>	,,
Mineral Surveyor, under order dated <u>January</u> examined and the necessary corrections massurveyor, the field notes and the survey	
James P. Kelley (Authorized Signature)	Chief Cadastral Surveyor of Arizona (Title)